Optimal Temperature Range for Your Moto Watch 70

Inas B. - 2025-10-08 - Product Features

To ensure your Moto Watch 70 works at its best, follow these temperature guidelines:

Operating Temperature:

- Safe range: **0°C to 45°C**
- Recommended range: **5°C to 35°C** for optimal performance

Storage Temperature:

- When not in use: **-20°C to 45°C**

Important Tips:

- Staying within these ranges protects the battery and overall performance.
- Avoid placing the watch near flammable or explosive materials.

Following these guidelines keeps your Moto Watch 70 reliable and efficient.