Charging Your Moto360 Battery

Inas B. - 2025-10-13 - Troubleshooting & Setup

Keep your Moto 360 powered up efficiently. The 3rd Gen Moto 360 smartwatch takes about **60 minutes to charge from 0% to 100%**. Using the **official charger** ensures the best performance and helps preserve battery longevity.

Tips for Optimal Charging:

- Charge on a **flat, cool surface**.
- Avoid using **non-certified chargers**.
- **Remove the watch from any case** if you notice slow charging.

 Pro Tip: Charging for shorter sessions throughout the day is fine—modern batteries don’t suffer from “memory effect.”